

In the specification:

Page 8, lines 14-23, please amend the paragraph as follows:

With reference to FIGS. 2 and 5, the marking portion (204) is formed on the bottom of the upper cavity (203) to mold the product indicator (101) on the front of the body of the tool bracket (10). Since the secondary flat molding surface of the upper cavity (203) is flush with the primary flat molding surface of the through cavity (201), a continuous parting line (102) is formed along the interface between the interchangeable mold (202) and the common mold (200) on the top, the bottom and the sides of the body of the tool bracket (10) and is free from the front of the body. Consequently, the parting line (102) is free and is not visible from the front of the body when a consumer faces the front of the tool suspension device. Therefore, the front of the body of the tool bracket (10) is clean and neat.